

Northwest Hydro-Fracturing

Increasing Woler Well Yield

Hydrefracturing

January 5, 2007

Well Rehabilitation

Well Dovelapment

To IDWR Rule Making Committee

I appreciated the opportunity to testify at the Video Conference January 4, 2007 concerning IDWR proposed regulations:

I have been licensed in Idaho since the late sixtv's.

In thousands of wells, drilling and hydrofracturing, I have not seen failure of PVC as a liner collapsing on the pumps.

To require that all PVC liners be sand packed or sealed is to regulate construction that is not the best design.

The current regulations handle the issue of liners very appropriately.

isnemsed and Bourled in Weehingen Idebe, Oregon and Mortana

you Darmannees Sinceredy,

Lynn Bartholomew

License # 52

13812 W. Lincoln Road Spokane WA 99224 509-466-3078 1-800-983-0998 FAX 509-467-2012 Eracili nwirce@june com